

**PROFORMA FOR THE SAFETY OF SCHOOL BUILDING
PART- 1**

(To be filled by the Head of School/ Institute)

1. Name of the School *Bhartiya Vidya Mandir Sr. Sec. School* :
2. Location *Kitchlu Nagar, Ludhiana.* :
3. Plot Area *5.27 (Acres) (25506.8) Sq Yards* :
4. Plinth Area *67574 Sqft.* :
5. Number of Storey's *Basement, Ground, 1st, 2nd & 3rd floor* :
6. Year of Construction of Building :
7. **If the building has been constructed under the supervision** :
Of the qualified Engineer, the following details may be given :
 - a) Name of the Engineer with qualification *SH. Roshay Sham Sharma* :
 - b) Address of Engineer *B/1/1086/Dandi Swami Chowk* :
 - c) Set of Structural drawings used in the construction, if available : *Yes.*
 - d) Name & address of Architect with qualification : *SH. Roshay*
8. **Whether the building has been constructed for the purpose** :
 - a) School : YES/ NO
 - b) Residential Purpose and converted for use as a School : YES/ NO
9. **Materials used for roofs** :
 - a) R.C.C. Slabs/R.B.C. Slabs : YES/ NO
 - b) R.S. Joist & Battons : YES/ NO
 - c) Wooden joists & Battons : YES/ NO
10. **Materials used for walls** :
 - a) Mud Mortar : YES/ NO
 - b) Cement Mortar : YES/ NO
 - c) Lime Mortar : YES/ NO
11. **Flooring** :
 - a) Conglomerate : YES/ NO
 - b) Terrazo : YES/ NO
 - c) Brick Paving. : YES/ NO
12. **A detailed drawing indicating dimensions of the rooms**
Alongwith size and location of doors and windows
(Attached)

Roshay
Principal
BHARTIYA VIDYA MANDIR
Kitchlu Nagar, Ludhiana.

PART-II
(To be filled by the S.D.E.)

- a) I have visited the above mentioned school on dated 09/05/2022 And have visually inspected it from all angles of safety and find it fit for normal use as School buildings.
- b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c) In case the building is affected by food, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d) This building can be safety occupied for normal use upto (indicate upto which it can be used) 31/03/2023


ਉਸਾਰੀ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
Sub Divisional Engineer,
ਲੇ. ਨਿ. ਵਿ. ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਲੁਧਿਆਣਾ।
6E

ਨੰਬਰ:- 58 - 59 ਮਿਤੀ:- 10/05/2022

- ✓ 1. ਪ੍ਰਿੰਸੀਪਲ **Bhartiya Vidya Mandir Senior Secondary School Kitchlu Nagar, Ludhiana** ਜੀ ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਜਾਣਕਾਰੀ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।
2. ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ. 1, ਲੇ. ਨਿ. ਵਿ., ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਲੁਧਿਆਣਾ ਜੀ ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਲੋੜੀਂਦੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।


ਉਸਾਰੀ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਉਸਾਰੀ ਮੰਡਲ ਨੰ: 3
ਲੇ. ਨਿ. ਵਿ. ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਲੁਧਿਆਣਾ।